

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors : Takeuchi et al.  
Serial No. : 10/542,645  
Filed : April 8, 2004  
Patent No. : 7,191,757 B2 - Issued March 20, 2007  
For : THROTTLE CONTROL IN INTERNAL COMBUSTION  
ENGINE FOR NOISE REDUCTION

REQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.322 & § 1.323

SIR:

It is respectfully requested that the enclosed certificate of correction be issued for the above Patent under authority of 35 USC §354 & §355.

The changes represent correction of typographical errors, some of which occurred during printing of the patent and others were not previously noticed by the applicants.

Please charge Deposit Account No. 11-0600 in the amount of \$100.00 to cover the fee under 37 C.F.R. 1.20(a). A copy of this request is enclosed for that purpose.

Respectfully submitted,

Dated: July 2, 2007

/Robert L. Hails, Jr./  
Robert L. Hails, Jr.  
Registration No. 39,702

KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, DC 20005  
Tel: (202) 220-4200  
Fax: (202) 220-4201

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

**PATENT NO.** : 7,191,757 B2 Page 1 of 1  
**DATED** : March 20, 2007  
**INVENTOR(S)** : Takeuchi et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>Column</u>	<u>Line</u>	
5	35	Change "dose" to --does--.
5	49	Change "toque" to --torque--.
6	59	Change "ω" to --ωt--.
8	35	Change "adventurously" to --advantageously--.
8	41	Change "toque" to --torque--.
8	47	Change "ωis" to --ω is--.
8	48	Change "ωis" to --ω is--.

**MAILING ADDRESS OF SENDER:**

Shawn O'Dowd  
KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, DC 20005

**Patent No.: 7,191,757 B2**